


L=450mm


L=600mm

L=750mm


# ANTIDARK




①




②




③




④



⑤




⑤-2



1:Strip cable jacket,copper wire length is 5mm,total stripped cable length is 12mm.

2:install the parts with cable,plug the wires into the connector and fix them.

⑥



⑦

